

## Factores de tablas de Control

Número de elementos en la muestra n	Tablas de promedios	Tablas de rangos			
	Factores de los límites de control	Factores de la línea central	Factores de los límites de control		
	A2	d2	D3	D4	
2	1.880	1.128	0	3.267	
3	1.023	1.693	0	2.575	
4	0.729	2.059	0	2.282	
5	0.577	2.326	0	2.114	
6	0.483	2.534	0	2.004	
7	0.419	2.704	0.76	1.924	
8	0.373	2.847	0.136	1.864	
9	0.337	2.97	0.184	1.816	
10	0.308	3.078	0.223	1.777	
11	0.285	3.173	0.256	1.744	
12	0.266	3.258	0.284	1.716	
13	0.249	3.336	0.308	1.692	
14	0.235	3.407	0.329	1.671	
15	0.223	3.472	0.348	1.652	